

# Inspection instructions

## EDELRID HMS Bulletproof Triple / Triple FG

The precautionary call for a safety check concerns both carabiner models with manufacturing codes 2018 01 and 2018 02:



HMS Bulletproof Triple  
73727



HMS Bulletproof Triple FG  
73728



Jul<sup>2</sup> Belay Kit  
Bulletproof Triple  
73732



Mega Jul Sport Belay Kit  
Bulletproof Triple  
73735

### 1 Checking the manufacturing codes

The manufacturing code is located on the outside of the closed carabiner spine.



If your carabiner is marked with a manufacturing code **2018 01** or **2018 02**, or if the manufacturing code is illegible, please perform the inspection as specified in section 2.



**CHECK**




Later batches (for example **2018 03** or **2019 01**) are not affected and can still be used.




**OK**

**2 Checking the rivet**

Please check that the rivet was fitted properly at the gate joint. On one side the rivet should have a head, on the other it should be pressed flat.



**RETURN**



**OK**

**Please mail to:**  
EDELRID GmbH & Co. KG  
Service  
Achener Weg 66  
88316 Isny im Allgäu  
Germany

**Questions?** Please read our Frequently Asked Questions (FAQs).